


Honda Civic

NLAFB8540FW002700

2015

PETROL

Moderate CO_2



Good

Mileage history and maintenance followed until 2021, but the mileage has not been verifiable for over 5 years.

Reassuring points

- Complete service history with 6 interventions recorded between 2016 and 2021.
- No history of theft reported in the consulted databases.

Points to watch

- Last known reading: 2021-09-25 (26,374 km): mileage not updated for over 2 years.

Summary by category 7 checks

We checked 800 data sources across 32 countries

+29

Theft	Mileage	Damage	CO_2 Emissions
✓ No history	⚠ Partially verified	✓ None	⚠ Moderate - 156

Safety recalls	Market Value	Safety
✓ None active	HUF 5,200,000 to 6,...	⚠ Unknown


This summary is generated automatically from the data available at the time of consultation. It does not constitute expert advice and does not engage CarJudge's liability. The information presented depends on the data provided by our suppliers and may be incomplete.

Mileage

We check for odometer rollbacks and inconsistencies.

⚠ **Last known reading: 09/25/2021 (26,374 km)**
No more recent reading is available: the current mileage cannot be verified.

Mileage over time



Mileage history

Source	Date	Mileage	Type	Operations
ATU Weiden, Dr.-Kilian-Straße 11, 92637 Weiden in der Oberpfalz, Germany	09/25/2021	26,374 km	Service	Oil and Oil filter Change. Inspect vehicle corrosion. *1: If item B appears before one year has passed, inspect for vehicle corrosion every year. External paintwork and panel corrosion check. Under body corrosion check.
Autohaus Markus Fugel E.K., Hofer Straße 7C, 09224 Chemnitz, Germany	09/30/2020	20,333 km	Service	Replace brake fluid. Oil and Oil filter Change. Inspect vehicle corrosion.

Source	Date	Mileage	Type	Operations
Autohaus Fugel GmbH, Annaberger Straße 275, 09125 Chemnitz, Germany	07/16/2019	19,255 km	Service	Replace brake fluid. Inspect vehicle corrosion.
Autohaus Fugel GmbH, Annaberger Straße 275, 09125 Chemnitz, Germany	07/27/2018	12,321 km	Service	Oil and Oil filter Change. Inspect vehicle corrosion. *1: If item B appears before one year has passed, inspect for vehicle corrosion every year. External paintwork and panel corrosion check. Under body corrosion check.
Autohaus Fugel GmbH, Annaberger Straße 275, 09125 Chemnitz, Germany	08/11/2017	6,053 km	Service	Inspect vehicle corrosion. *1: If item B appears before one year has passed, inspect for vehicle corrosion every year. External paintwork and panel corrosion check. Under body corrosion check.
Delivery	08/29/2016	5 km	Service	

Theft

We check police databases worldwide to see if this vehicle is declared stolen or not.

No theft records found

This vehicle is not declared stolen in any database we checked.

We checked in Ireland and 22 other countries:



Vehicle Comparison

Discover how this vehicle compares to similar models in the same category

Summary

1 Space Efficiency

The Honda Civic offers the best rear legroom in this group, making it the most suitable choice for passengers, while the Corolla provides the largest cargo capacity for luggage.

2 Performance vs Efficiency

The Mazda 3 provides the highest power and best acceleration, though it sacrifices some fuel efficiency compared to the Civic's optimized drivetrain.

3 Urban Maneuverability

Both the Hyundai Elantra and Mazda 3 feature a tighter turning radius (5.3m) compared to the Civic (5.6m), giving them a slight edge in dense city parking scenarios.

Feature Comparison

Best value in the row

Feature	Honda Civic IX Sedan (FB) This vehicle	Toyota Corolla (E170)	Hyundai Elantra (MD)	Mazda 3 Sedan (BM)
Power (hp)	142	132	148	155
Torque (Nm)	174	160	178	200
Acceleration (s) 0-100 km/h	9	10.5	9.8	8.5
Top Speed (km/h)	200	195	202	210
Consumption (L/100 km)	6.1	6.4	7.4	6.9
CO_2 Emissions	156 g/km	148 g/km	171 g/km	159 g/km
Transmission	6-speed manual	CVT	6-speed automatic	6-speed automatic
Fuel Type	PETROL	Petrol	Petrol	Petrol
Fuel Tank Capacity	50 L	50 L	48 L	50 L
Safety Features	ABS, Vehicle Stability Assist, Multiple Airbags, ISOFIX	VSC, TRAC, ABS, 8 Airbags	ESC, TCS, ABS, 6 Airbags	Dynamic Stability Control, TCS, ABS, Blind Spot Monitoring

Feature	Honda Civic IX Sedan (FB) This vehicle	Toyota Corolla (E170)	Hyundai Elantra (MD)	Mazda 3 Sedan (BM)
Parking Sensors	Standard rear camera, optional rear sensors	Standard rear camera	Optional rear camera	Standard rear camera
Trunk Capacity	440 L	452 L	420 L	419 L
Turning Radius	5,600 mm	5,400 mm	5,300 mm	5,300 mm
Rear Legroom	940 mm	920 mm	900 mm	890 mm
Typical Driver Use Case	Commuting and family transport	Reliability-focused family use	Urban driving and value-based commuting	Driver-focused compact transportation

Vehicle Specifications

Key technical data such as engine, transmission, and performance.

Engine Details

Engine	R18Z4,R18Z1
Displacement	1,798

Interior Space

Seating Capacity	5 seats

Towing & Weight

Gross Weight	1,680

Brakes

ABS	ABS

Fuel

Fuel Type	PETROL

Dimensions

Length	4,545
Width	1,755
Height	1,425
Wheelbase	2,675

Tires

Front Tire Size	205/55 R16 85H

Manufacturing Details

Official specifications and details from the manufacturer

Verify specifications

Manufacturing details are based on the VIN and may vary by market or trim level. Always verify with the seller.

Make **Honda**	Model **Civic**	Body Type **A trois volumes**	Manufacturing Year **2015**
Vehicle Type **Car**	Country of Origin **Turkey**		

5 fields not available for this vehicle

Recalls


We checked all safety recalls issued for this vehicle and listed them here so you can confirm with the seller whether they've been completed.

No recalls found
This vehicle has no open safety recalls on record.

Market Value

Computed estimate

We estimate this vehicle's value on the used market from its characteristics: make, model, year, mileage, fuel type and country.




Indicative estimate - not contractual

Estimate computed from the vehicle's characteristics, in the absence of sufficient market data for this vehicle.

Maintenance Costs

Estimate calculated

Estimate of the usual annual maintenance costs for this vehicle in Hungary: service, oil change, tires and roadworthiness test.



Cost breakdown

Service Annual manufacturer service	HUF 40,000 to 75,000 43% of budget	**Oil change** Oil and filters	HUF 35,000 to 55,000 33% of budget
Tires Wear spread over the year	HUF 15,000 to 25,000 15% of budget	**Roadworthines...** Mandatory every 2 years - cost spread per year	HUF 10,000 to 15,000 9% of budget

Indicative estimate - non-binding

Estimate based on the vehicle characteristics and the average rates charged in your country (Hungary).

Equipment

Factory-installed features and optional extras included with the vehicle.

✓ Included

Safety

✓ ABS Brakes

Emissions

We have reviewed this vehicle's CO_2 emissions and the associated taxes or costs that may apply.

Vehicle subject to a higher tax

This vehicle has moderate emissions, which means you may pay more tax depending on the local regulations.

CO_2 emissions

156 g CO_2/km



Manufacturer Maintenance Schedule

AI estimate

Operations scheduled by the manufacturer at each mileage milestone. The annual budget is estimated in the "Maintenance Costs" section.

15,000 km

- Replace engine oil and filter
- Inspect tie rod ends, steering gear box, and boots
- Inspect driveshaft boots
- Inspect front and rear brakes
- Inspect suspension components

30,000 km

- Replace engine oil and filter
- Inspect front and rear brakes
- Replace dust and pollen filter
- Inspect suspension, steering, and driveshaft boots

45,000 km

- Replace engine oil and filter
- Replace brake fluid
- Replace air cleaner element
- Inspect front and rear brakes

60,000 km

- Replace engine oil and filter
- Inspect front and rear brakes
- Replace dust and pollen filter
- Inspect suspension, steering, and driveshaft boots

75,000 km

- Replace engine oil and filter
- Inspect tie rod ends, steering gear box, and boots
- Inspect front and rear brakes

90,000 km

- Replace engine oil and filter
- Replace dust and pollen filter
- Inspect front and rear brakes
- Replace air cleaner element
- Replace brake fluid

105,000 km

- Replace engine oil and filter
- Replace spark plugs
- Inspect valve clearance
- Inspect front and rear brakes

120,000 km

- Replace engine oil and filter
- Replace dust and pollen filter
- Replace manual transmission fluid (if applicable)
- Replace automatic transmission fluid (if applicable)
- Inspect front and rear brakes
- Inspect suspension, steering, and driveshaft boots

Typical manufacturer schedule

No schedule is available for this vehicle. This one is the typical schedule of the model and engine, estimated by AI: it is not specific to this vehicle.

What this report cannot guarantee

This report brings together what our sources have recorded about this vehicle. Anything that was never declared or recorded cannot appear in it.

Odometer fraud

No report can guarantee that it will detect a tampered odometer. We compare the mileage readings recorded by our sources: an inconsistency is a strong signal, but the absence of inconsistencies does not prove that the odometer is original.

Unreported accidents

An accident repaired without going through an insurer, an appraisal or an auction does not appear in any database. If we find no accident, it does not mean the vehicle has never had one.

Coverage by country

The information available depends on the country of registration. Some countries make the official vehicle inspection history public, others do not. Here is what we were able to check for this vehicle.

For this vehicle (search country: Hungary)

Mileage	6 readings found	Source: sales, listings and servicing
Theft	No theft report found	
Auction sales	No sale found	
Service history	6 service records found	
Official vehicle inspections	Not covered for this country	

Before buying, have the vehicle inspected by a professional and ask the seller for the service invoices and the vehicle inspection reports.

Gallery

